


Internal Inspection of Sprinkler System Piping



An automatic sprinkler system must have a reliable pipe system for optimal operation. Maintenance requirements in sprinkler standards therefore outline that internal pipe inspections are required periodically.

Kiwa R2B will open sections of the sprinkler system piping at strategic locations during the inspection of the piping system.

A representative part of the sprinkler system is inspected with a camera. Results are summarised in an extensive inspection report. This provides insight into the current condition of your sprinkler system and if necessary you can start follow-up actions.

Why Kiwa R2B?

Kiwa R2B is a leading Inspection Institution in the area of Fire Safety and Security (FSS), providing services with expertise, flexibility, customer-focus and innovative attitude. We conduct inspections and provide training maintaining our fully independent, unbiased and fair position.

Kiwa R2B operates in a wide range of facilities, including health care, tunnels, logistical, industrial, (petro) chemical, data centres, airports, storage of hazardous goods and hotels.

Kiwa N.V.

Sir Winston Churchill-laan 273
2288 EA Rijswijk
P.O. Box 70
2280 AB Rijswijk
info@kiwa.nl